



COMPLETED ASSEMBLY



Item Qty.	Part Number	Description
1 4	BF304A	BOLTED FLANGE PLUG
2 4	BF306	3/8-16 X 3" HHCS
3 1	BF201BD	B.F. BACK PLATE B.D.
4 4	BF200GFV	B.F. BTM DRAIN GASKET
5 1	BF200GV	2" B.F. GASKET
6 1	V20156	2" TANK FLANGE
7 4	V20018	3/8" LOCK WASHER
8 4	V20019	3/8-16 HEX NUT



21SEPT99



BANJO CORPORATION
150 BANJO DR. * CRAWFORDSVILLE, IN 47933

PART NO.

BF200BDV

TITLE

**2" BLIND HOLE
BOTTOM DRAIN TANK FLANGE**

THIS DRAWING AND ALL INFORMATION CONTAINED THEREON ARE THE EXCLUSIVE PROPERTY OF BANJO CORPORATION. UNLESS SPECIFICALLY NOTED, THIS DRAWING AND ITEMS SHOWN ON THIS DRAWING ARE SUBJECT TO CHANGE AT ANY TIME.